

গণপ্রজাতন্ত্রী বাংলাদেশ সরকার  
স্বরাষ্ট্র মন্ত্রণালয়



বাংলাদেশ কোস্ট গার্ড, জোনাল কমান্ডার পূর্ব জোন, মৎস্য বন্দর, চট্টগ্রাম

উন্মুক্ত দরপত্র বিজ্ঞপ্তি

১।	মন্ত্রণালয়/ডিভিশন	স্বরাষ্ট্র মন্ত্রণালয়				
২।	সংস্থার নাম	বাংলাদেশ কোস্ট গার্ড (পূর্ব জোন)				
৩।	দরপত্র আহবায়ক	জোনাল কমান্ডার পূর্ব জোন, বাংলাদেশ কোস্ট গার্ড				
৪।	দরপত্র আহবায়কের ঠিকানা	জোনাল কমান্ডার পূর্ব জোন, বাংলাদেশ কোস্ট গার্ড, মৎস্য বন্দর, চট্টগ্রাম				
৫।	দরপত্রের বিষয়বস্তু	বাংলাদেশ কোস্ট গার্ড পূর্ব জোনের অধীনস্থ বিসিজি স্টেশান কক্সবাজার পন্টুন (এস-১৫০৮) রিফিট/ডকিংপূর্বক মেরামত প্রসঙ্গে।				
৬।	দরপত্র বিজ্ঞপ্তি নং ও তারিখ	৪৪.০৮.১৫৬১.২০০.২৪.০০২.২১.৪৩৯৬ তারিখ ০২ ডিসেম্বর ২০২১				
<b>গুরুত্বপূর্ণ তথ্যাদি</b>						
৭।	দরপত্রের ক্রয়ের পদ্ধতি	উন্মুক্ত দরপত্র পদ্ধতি (OTM)				
<b>ফান্ড তথ্যাদি</b>						
৮।	বাজেট ও তহবিলের উৎস	গণপ্রজাতন্ত্রী বাংলাদেশ সরকার				
<b>বিশদ তথ্যাদি</b>						
৯।	দরপত্র প্যাকেজের নাম	বাংলাদেশ কোস্ট গার্ড পূর্ব জোনের অধীনস্থ বিসিজি স্টেশান কক্সবাজার পন্টুন (এস-১৫০৮) রিফিট/ডকিংপূর্বক মেরামত প্রসঙ্গে।				
১০।	দরপত্র বিজ্ঞপ্তি প্রকাশনা ও বিক্রি শুরু তারিখ	০৮ ডিসেম্বর ২০২১ এবং বিক্রি শুরু ১২ ডিসেম্বর ২০২১				
১১।	দরপত্র তফসিল বিক্রির শেষ তারিখ	০১ জানুয়ারি ২০২২	বেলা ১৪০০ ঘটিকা পর্যন্ত			
১২।	দরপত্র তফসিল জমা দানের শেষ তারিখ	০২ জানুয়ারি ২০২২	বেলা ১২০০ ঘটিকা পর্যন্ত			
১৩।	দরপত্র খোলার তারিখ ও সময়	০২ জানুয়ারি ২০২২	বেলা ১৩০০ ঘটিকা			
১৪।	অফিসের নাম ও ঠিকানা	জোনাল কমান্ডার পূর্ব জোন, বাংলাদেশ কোস্ট গার্ড, মৎস্য বন্দর, চট্টগ্রাম				
১৫।	দরপত্র বিক্রয়ের ঠিকানা					
১৬।	দরপত্র জমা দেওয়ার ঠিকানা	গার্ড রুম, বিসিজি বেইস চট্টগ্রাম, মৎস্য বন্দর, চট্টগ্রাম				
১৭।	দরপত্র খোলার ঠিকানা					
১৮।	প্রি-টেন্ডার মিটিংয়ের স্থান, তারিখ ও সময়	প্রযোজ্য নয়				
<b>দরপত্রের তথ্য</b>						
১৯।	দরপত্রের অংশগ্রহণের যোগ্যতা	একই ধরনের কার্য সম্পাদনের ক্ষেত্রে ন্যূনতম ০৩ বৎসরের সার্বিক যোগ্যতা থাকতে হবে।				
২০।	পণ্যের সংক্ষিপ্ত বর্ণনা	ক্রঃ নং	কাজের বিবরণ	একক	পরিমাণ	মন্তব্য
		১.	Pontoon S-1508 to be docked and on completion of necessary repair work pontoon to be undocked as necessary with dock rent. (L-30 m, B-8.5 m, H-2 m).	প্যাকেজ	০১	
		২.	Under water hull plate, above water line and deck plate including all area are to be cleaned by water jets and blasting as necessary. approx. area 850 Sq. Mtr. Material- MS	প্যাকেজ	০১	

৩.	Under water hull, above water hull boot topping area, upper deck and super structure are to be painted with marine grade appropriate scheme of paint as necessary.	প্যাকেজ	০১	
৪.	Under water Hull plate above the water line including deck super structure plate to be surveyed and ultrasonic gauge, gauging point. Defective plates are to be removed as necessary. Shell expansion drawing followed. Appox. Mtr (Thickness 8 mm). 100 point	সংখ্যা	১০০	
৫.	Port side deck plate perforated appox. area (28X1.50) Mtr. Mat. MS plate. (Thickness 6 mm)	টন	১.৫	
৬.	Stbd side deck plate perforated appox. area (28X1.50) Mtr. Mat. MS plate. (Thickness 6 mm)	টন	১.৫	
৭.	Deck plate Fwd side perforated. Area (3X4) Mtr. Mat. MS plate. (Thickness 6 mm)	টন	১.২	
৮.	Deck plate Aft side perforated. Area (3X4) Mtr. Mat. MS plate. (Thickness 6 mm)	টন	১.৪	
৯.	Deck plate Infront of DG room perforated. Area (8X5.50) Mtr. Mat. MS plate. (Thickness 6 mm)	টন	০১	
১০.	Defective Plates of underwater hull Appox area (14X4.40) Mtr. MS plate. (Thickness 8 mm) MS Approx-9.4 Ton. After Ultrasonic gauging of Underwater hull area defective plate are to be Renewed/Replaced as necessary.	টন	০৭	
১১.	All Zinc anodes are to be surveyed and renewed if wasted beyond 50% (zinc anode measurement- 200X100X40mm)	প্যাকেজ	০১	
<b>B. HULL AND MISCELLANEOUS</b>				
১২.	16 in no bollard perforated. Bollard are to be repaired/renewed as necessary Size: (0.75X0.30) mtr. Material- MS Electrode rod.	সংখ্যা	১৬	
১৩.	08 in no bollard base perforated. Bollard base are to be repaired/renewed as necessary Size: (1.50X0.50) Mtr. Material- MS Electrode rod.	সংখ্যা	০৮	
১৪.	Port side Fender line perforated. Fender line to be repaired/renewed as necessary Size: L-30m, Dia-10 inch. Material- MS plate.	সংখ্যা	০১	
১৫.	Stbd side Fender line perforated. Fender line to be repaired/renewed as necessary Size: L-30m, Dia-10 inch. Material- MS plate.	সংখ্যা	০১	
১৬.	06 in no Fair Leak base perforated. Fair Leak base to be repaired/renewed as necessary Size: (18X08) inch. Material- MS Electrode rod	সংখ্যা	০৬	
১৭.	01 in no ladder perforated. Ladder to be repaired/renewed as necessary. Size: (LxB=14'x2.5') Material- MS plate.	সংখ্যা	০১	
১৮.	06 in no MS door & door rubber seal perforated. Door to be repaired/renewed as necessary. Size: HxB-(7x2.5)Ft	সংখ্যা	০৬	
১৯.	06 in no MS door lock defective. Lock to be renewed as necessary.	সংখ্যা	০৬	
২০.	10 in no window perforated. Window to be repaired/ renewed as necessary. Size: (LxB=2'x2') Material- MS	সংখ্যা	১০	
২১.	02 in Fresh water tanks inspect need to be cleaned and cement wash as necessary.	সংখ্যা	০২	
২২.	70 in no stanchion shoe perforated. Stanchion shoe to be repaired/renewed as necessary. Size: each 1 Ft, Dia-1.5 inch, Material- GI Pipe.	সংখ্যা	৭০	
২৩.	03 in no stanchion Pipe perforated. Stanchion pipe to be repaired/renewed as necessary. Size: L-2.5 Ft, Dia-1.25 inch, Material- GI Pipe.	সংখ্যা	০৩	
২৪.	Following MS/SS/Wooden item. Repaired/renewed as necessary. Inspect MS/SS/Wooden item.			
	<b>Ser.</b>	<b>Name of MS/SS Item</b>		
	01	Sailor Double Bunk (7x3x2) Ft. Material- MS.	সংখ্যা	০৮
	02	Sailor Double Locker (3x1.5x6) Ft. Material- SS.	সংখ্যা	০৪
	03	Dining Chair (3x1.5x1.5) Ft. Material MS/wooden.(otobi)	সংখ্যা	০৬
		<b>Name of Wooden Item</b>		
	04	Dining table (7x3x3) Ft. Wooden	সংখ্যা	০১
	05	Table (4x2.5x2.5) Ft. Wooden	সংখ্যা	০১
	06	Shoe Rack (3x1x3) Ft. Wooden	সংখ্যা	০১
২৫.	08 in drain Pipe blocked. Pipe to be cleaned as necessary.	সংখ্যা	০৮	
২৬.	Ventilation of Various Place defective. Ventilation to be repaired/renewed as necessary.	প্যাকেজ	০১	

২৭.	Sailor accommodation, Galley, DG room, Kitchen, Overhead and side wooden paneling deteriorated. Wooden paneling to be repaired/renewed as necessary. appox. Area 220 Sq. Mtr. Mat - ½" plywood, wood gorgon.	কয়ার মিটার	২২০	
২৮.	Sailors wash room tiles broken. Tiles to be renewed as necessary. appox. Area 85 Sq. Ft.	কয়ার ফুট	৮৫	
২৯.	12 in no hatch coming cover perforated. Hatch coming Cover to be repaired/renewed as necessary. Size (LxBxH=2'x2'x.5') each. Mat- MS.	সংখ্যা	১২	
৩০.	24 in no stub with nut worn out. Stub with nut renewed as necessary. Mat- MS & SS.	সংখ্যা	২৪	
৩১.	06 in no exhaust fan base perforated. Exhaust fan base repaired as necessary. Size (LxB=2'x1.5') each. Mat- MS.	সংখ্যা	০৬	
৩২.	14 in no vent pipe perforated. Vent pipe repaired as necessary. Mat- MS.	সংখ্যা	১৪	
৩৩.	02 in no Manhole cover perforated. Area (0.60X0.63) Mtr. MS plate.	সংখ্যা	০২	
৩৪.	10 in no Hatch cover rubber seal defective. Rubber seal to be repaired/renewed as necessary.	সংখ্যা	১০	
৩৫.	20 in no Hatch cover butterfly nut perforated. Butterfly nut to be repaired/renewed as necessary.	সংখ্যা	২০	
৩৬.	32 in no Hatch cover nut & bolt perforated. Nut & bolt to be repaired/renewed as necessary.	সংখ্যা	৩২	
৩৭.	10 in no Hatch ladder perforated. Hatch ladder to be repaired/renewed as necessary. Mat-MS plate/round bar.	সংখ্যা	১০	
৩৮.	02 in no Ladder perforated. Ladder to be repaired/ renewed as necessary. Mat-MS plate/round bar.	সংখ্যা	০২	
৩৯.	02 in no Fire hose securing box perforated. Box to be repaired/ renewed as necessary.	সংখ্যা	০২	
৪০.	03 in Fire hydrant valve defective. Valve to be repaired/renewed as necessary.	সংখ্যা	০৩	
৪১.	Fwd side betting line perforated. Area (8.5x0.31) Mtr. Mat. MS plate.	টন	১.২	
৪২.	Aft side betting line perforated. Area (8.5x0.31) Mtr. Mat. MS plate.	টন	১.২	
৪৩.	01 in no Low commode perforated. Commode to be repaired/renewed as necessary.	সংখ্যা	০১	
৪৪.	01 in no Flash pipe perforated. Pipe to be repaired/renewed as necessary.	সংখ্যা	০১	
<b>C. ENGINEERING</b>				
৪৫.	01 in no Portable Diesel Pump to be Renewed as necessary.	সংখ্যা	০১	
৪৬.	01 in no Submersible Pump to be Renewed as necessary.	সংখ্যা	০১	
৪৭.	03 in no Window Type AC to be Replace/Renewed as necessary (Recondition General AC).	সংখ্যা	০৩	
৪৮.	01 in no Pump With Motor (Pedrollo, 2 HP, 1.5 KW) for Fresh Water Supply to be Replace/Renewed as necessary	সংখ্যা	০১	
৪৯.	Rubber Hose Pipe for Fresh Water Supply to be Replace/Renewed as necessary. Size: L-100 Mtr, Dia-1 inch.	মিটার	১০০	
৫০.	Synthetic Hose Pipe With Nozzle (Male-Female) for Fire Fighting to be Replace/Renewed as necessary. Size: L-50x4 Mtr, Dia-2 inch. Appox. Length 200 Mtr.	প্যাকেজ	০১	
৫১.	06 in no CO <sub>2</sub> Fire Fighting Extinguisher (5 kg) to be renewed as necessary.	সংখ্যা	০৬	
৫২.	06 in no Foam type Fire Fighting Extinguisher (10 ltr) to be renewed as necessary.	সংখ্যা	০৬	
৫৩.	06 in no ABC Dry Powder Fire Fighting Extinguisher (03 Kg) to be renewed as necessary.	সংখ্যা	০৬	
<b>D. ELECTRICAL &amp; RADIO ELECTRICAL</b>				
৫৪.	Sailors' accommodation Electric wiring defective. Sailors' accommodation Electric wiring defect to be rectified/ renewed as necessary.	সংখ্যা	০১	
৫৫.	04 in no LED search light defective. Light to be repaired/renewed as necessary.	সংখ্যা	০৪	
৫৬.	04 in no Energy/LED light with cover defective. Energy/LED light with cover renewed as necessary.	সংখ্যা	০৪	
৫৭.	01 in main switch board defective. Main switch board defect to be rectified/ renewed as necessary.	সংখ্যা	০১	
<p><b>বিশেষ দৃষ্টব্যঃ</b> মেরামত পরবর্তী সময়ে পন্থনের পরিবর্তন ও পরিবর্ধন এবং মেরামত কার্য সম্পাদনকালীন সকল অব্যবহার্য Scrap আইটেম সমূহ দরপত্র আহ্বানকারী প্রতিষ্ঠানের নিকট সুস্পষ্ট তালিকাসহ হস্তান্তর করতে হবে।</p>				

২১।	পণ্যের সংশ্লিষ্ট সেবা (সার্ভিস) এর বর্ণনা	প্রযোজ্য নয়			
২২।	দরপত্রের মূল্য	১,০০০/০০ (টাকা এক হাজার মাত্র) অফেরত যোগ্য			
২৩।	লট নং	লট পরিচিতি	দরপত্র জামানত	নিরাপত্তা জামানত	কার্য সমাধান
	(০১)	বাংলাদেশ কোস্ট গার্ড পূর্ব জোনের অধীনস্থ বিসিজি স্টেশন কক্সবাজার পল্টুন (এস-১৫০৮) রিফিট/ডকিংপূর্বক মেরামত প্রসঙ্গে।	টাকা ১,৯৪,৩৪০/০০ (পে অর্ডার এর মাধ্যমে দরপত্র দাখিলের সময় প্রদান করতে হবে)	১০% (পে অর্ডার এর মাধ্যমে)	০৪ সপ্তাহ (চুক্তি স্বাক্ষরের পর হতে)
২৪।	আহবায়কের নাম	জোনাল কমান্ডার পূর্ব জোন, বাংলাদেশ কোস্ট গার্ড, মৎস্য বন্দর, চট্টগ্রাম			
২৫।	পদবী	ক্যাপ্টেন বিএন			
২৬।	আহবায়কের ঠিকানা	কার্যালয়, জোনাল কমান্ডার পূর্ব জোন, বাংলাদেশ কোস্ট গার্ড, মৎস্য বন্দর, চট্টগ্রাম			
২৭।	ফোন নম্বর	মোবাঃ ০১৭৬৯-৪৪২০৩৫, ০১৭৬৯-৪৪২১১৯।			
২৮।	বিশেষ নির্দেশাবলী	<p>ক। কোস্ট গার্ড কর্তৃপক্ষ কোন কারণ দর্শানো ব্যতিরেকে যে কোন দরপত্র গ্রহণ বা বাতিল অথবা সকল দরপত্র বাতিল করার অধিকার সংরক্ষণ করেন।</p> <p>খ। নিজস্ব ডকইয়ার্ড থাকলে অগ্রাধিকার পাবে/ বিসিজি বেইস চট্টগ্রামের নিকটবর্তী যে কোন ডকইয়ার্ড/ শীপইয়ার্ড এ রিফিট/ডকিং কার্যক্রম সম্পন্ন করতে হবে।</p> <p>গ। নিজস্ব শীপইয়ার্ড না থাকলে অন্য কোন প্রতিষ্ঠানের শীপইয়ার্ডে কার্যক্রম সম্পন্ন করতে হবে।</p> <p>ঘ। নৌবাহিনী/ কোস্ট গার্ড/ বিজিবি/ বিআইডব্লিউটি/ সরকারী সংস্থার জলযান নির্মাণ/ মেরামতের অভিজ্ঞতার সনদ দাখিল করতে হবে।</p> <p>ঙ। মুদ্রণ জনিত ত্রুটি অথবা অন্য কোন কারণে কোন ধরনের সন্দেহের উদ্বেক হয়ে থাকলে সে ক্ষেত্রে দি পাবলিক প্রকিউরমেন্ট বিধিমালা ২০০৮ ও উহার সর্বশেষ সংশোধনী এর বিধান প্রযোজ্য হবে।</p> <p>চ। অনিবার্য কারণ বশতঃ তফসিল বিক্রয়, টেন্ডার জমাধান এবং খোলার তারিখ বিঘ্নিত হলে তা পরবর্তী কার্য দিবসে অনুষ্ঠিত হবে।</p> <p>ছ। বিল দাখিলের সময় সর্বশেষ সরকার কর্তৃক জারীকৃত বিধি মোতাবেক ধার্যকৃত VAT এবং IT কর্তন করা হবে।</p>			



কাজী শাহ আলম  
ক্যাপ্টেন বিএন  
জোনাল কমান্ডার পূর্ব জোন